

An Autonomous Institution

Approved by AICTE, New Delhi
Affiliated to JNTU Kakinada
Accredited by NBA (UG: CSE,ECE,EEE,ME,CE & IT)
Accredited by NAAC(UGC) with A+ Grade
Recognised by UGC Under Section 2(f) & 12(B)
TEQIP Participated College
Recognised by Scientific & Industrial Research Organisation(SIRO)

4.4.2

There are established systems and procedures for maintaining and utilizing physical, academic and support facilities — classrooms, laboratory, library, sports complex, computers, etc.

Additional Information:

CONTENTS

S.No	Description	Pages
1	Infrastructure Maintenance Policy	1-8
2	Electrical and Plumbing Maintenance	9-84
5	Computers and Accessories Maintenance	85-96





INFRASTRUCTURE MAINTENANCE POLICY

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

K.Kotturu, Tekkali, Srikakulam District-532201

TABLE OF CONTENTS

S. No	CONTENT	Page
1	Introduction	3
2	Maintenance of Physical Facilities	4
2.1	Maintenance of Classrooms, Furniture and Laboratories	4
2.2	Maintenance and Utilisation of Library and Library	4
	Resources	
2.3	Maintenance and Utilisation of Seminar Halls and Auditoria	5
3.	Maintenance of ICT Facilities	5
4	Maintenance of Lab Equipment	6
4.1	Maintenance and Utilization of Advanced Research Lab	6
	and the Central Instrumentation Lab	
5	Maintenance of Sports and Games Facility	6
6	Maintenance of Campus Cleanliness	7
7	Maintenance of other amenities	7
8	Annual Stock Checking	7
9	Replacement of Equipment/ Electronics /Computers	7
10	Day to Day Emergency Maintenance	8

1. Introduction

The college is marching ahead under the able guidance of Chairman Rtn (PHF) Dr. K. Someswara Rao who is a Paediatrician by profession and committed to social service with a special reference to technical education with unstinted support from the Secretary Sri. L.L. Naidu, Director Prof. V.V. Nageswara Rao and other members of the Sri Aditya Educational Society.

Aditya Institute of Technology and Management currently offer 6 U.G programs in the disciplines of ECE, CSE, IT, EEE, CE and MECH, P.G program in MBA, and 6 disciplines of M. Tech. The total sanctioned intake per year is 900 in B. Tech programmes, 60 in MBA and 60 in M. Tech. The college is affiliated to JNTU Kakinada and hence follows the curricula prescribed by the Boards of Studies of the affiliating university. Based on industry and student feedback, the college faculties interact with university in updating the curriculum time to time.

The college has a total built-up area of 3867.79 Sq.m with 69 class rooms, 6 seminar halls of different sizes, and 59 laboratories. The current annual budget of the college is of the order of about Rs. 2803 lakhs. The College Library has about 52,851 volumes of books and has also a Digital Library with 74 journals as hard copies and 243 journals on-line. All the laboratories are provided with the state of art equipment namely computer labs, internet centre, language lab and digital library. The college has 125 KVA, 24 hours power supply from A.P. State Electricity Board. Besides this the college has three generators with a capacity of 325 KVA, 125 KVA and 62 KVA with 30 UPS of total capacity 143.5 KVA to ensure uninterrupted power supply for the smooth functioning of all routine academic activities. Hostel accommodation is available for about 561 boys and 278 girls in separate hostels. Sports facilities are available with play fields in all major games and sports spread over an area of about 5 acres.

The pass percentage has been consistently around 80% right from the inception of the college with some university ranks. The placement record for the previous three years has been laudable about 85% of eligible candidates get placed in various campus recruitment drives. The institute is always quality conscious and got NBA Accreditation for all B.Tech programs and NAAC Accreditation with A+ grade. Its commitment towards quality and growth enabled AITAM to become a TEQIP funded institution, in Andhra Pradesh in 2011.

The management provides whole-hearted support for the improvement of the college in all aspects. About 90 lakhs of rupees are allotted every year for augmenting / modernizing the equipment to pursue M. Tech, Ph. D. works by giving them study leaves and financial assistance. The faculty and students are closely associated with all administrative and academic policy decisions through membership on appropriate committees.

This document provides a management framework and an outline on the allocation of responsibilities to ensure effective use and maintenance of existing infrastructure facilities.

2. Maintenance of Physical Facilities

The physical facilities are maintained by Central Maintenance team associated with Estate Manager, System administrator, Supervisor (Civil works), Supervisor (Electrical works) and Technicians. The services of plumbers, electricians, and computer analysts are available in the campus for the uninterrupted power supply and maintenance of equipment like generator sets, general lighting, power distribution system, solar panels etc. Maintenance of water plumbing plants, sewage and drainage is undertaken by supporting staff. Supervisor (civil works) monitors the maintenance and cleanliness of the buildings, classrooms, labs, furniture, campus ground, sports facilities, staff lounge, students amenity areas, cafeteria and hostel buildings. Transport facilities are monitored and maintained by the Transport Coordinator and team. Annual maintenance of all vehicles is done promptly at the end of the academic year.

2.1. Maintenance of Classrooms, Furniture and Laboratories

Classrooms with furniture, teaching aids and laboratories are maintained by the respective department staff and attendants under the supervision of department Heads. Laboratory assistants take care of their respective laboratories. The Heads of Departments report to the administration for all the maintenance works periodically. Minor repairs are registered in a ledger maintained in the office and are attended on priority basis. Staff of respective department monitor effective utilisation of the laboratories. Students optimally utilize all classrooms during the daylong working hours and are also mentored to upkeep the furniture.

2.2. Maintenance and Utilisation of Library and Library Resources

The library staff is clearly instructed in the care and handling of library documents, particularly during processing, shelving and conveyance of documents. The steps taken are as follows:

- Bound volumes are not to be sorted out from their fore edges, as this process weakens the binding.
- Shelves should not be fully packed. A too-full shelf can crack spines and cause damage when a reader tries to remove a volume. Huge volumes need to be kept flat.
- Dust should not be allowed to deposit on the documents because the collection of dust causes staining of documents and promote chemical and biological problems.
- Cleaning and using vacuum should be done regularly and carefully.
- Magnetic discs or documents containing disc(s) should not be kept open or near any magnetic or electric equipment, i.e. tape recorders, air-conditioners, etc. Such materials should be kept in a dust-free, temperature and humidity controlled room.
- Proper pest management is done to minimize the problems caused by insects. Borax
 or common salt is used to prevent cockroaches. Sodium fluoride is applied to bound volumes
 to save them from silverfishes.
- Spread of kerosene oil, DDT or gammaxine powder over the affected area can help in removal of termites or white ants.
- Proper cleaning, fumigation and exposure to sunlight to the documents are done to reduce the effect of insects in the library.
- Repellants are used to save materials from Rats.

2.3. Maintenance and Utilisation of Seminar Halls and Auditoria

Seminar halls and auditoria are under the purview of the civil and electrical technicians and the cleanliness is taken care of by the housekeeping team. Effective utilisation of seminar halls and auditoria for organising academic meetings, seminars, conferences and cultural events is made. For accessing the facilities, the organising faculty/staff member submits a form through HOD and Dean and the date of event is registered and the halls are accessed on priority basis.

3. Maintenance of ICT Facilities

In Campus, E — services team comprising of System administrators, networking administrator and technical staff to maintain the ICT facilities including computers and servers. The annual maintenance includes the required software installation, antivirus and

upgrading. To minimise e-waste, electronic gadgets like projectors, computers, printers, photocopiers are serviced and reused. Campus Wi-Fi is maintained by respective centre.

4. Maintenance of Lab Equipment

The respective faculty members, staff, lab assistants and other service personnel are given responsibility to maintain the equipment under their purview. Stock registers, asset registers, log books, tools and plant registers are maintained by the respective laboratories to report entries and defects arising for rectification. All major repairs are identified and external expertise sought for maintenance of equipment wherever necessary with the permission of the Head of the Institution.

Standard operating procedures for all high end equipment is made available to the users. Incampus, users register in the log books and are responsible for the safe handling of the equipment. Breakage and repair if any, are reported to the Head of Department or the faculty-in-charge as the case may be and suitable measures are taken for speedy functioning of the equipment. Breakage of glassware intended for use by students and scholars is entered in the breakage register and charges levied based on the cost of the equipment payable by the students at the end of the year and by the research scholars at the culmination of the course programme.

4.1 Maintenance and Utilisation of Advanced Research Lab and the Central Computing Lab

Advanced research labs with sophisticated equipment are operated for the benefit of the research scholars. They are maintained by a faculty-in-charge who reports to the corresponding Dean/HOD on all matters related to working, maintenance, in-campus service and outsourcing of the equipment. Entry to the labs is through log book registration. Users must duly submit a service requisition form to the concerned HOD. Access to equipment and service for recording analytical and computational data is given on first-cum- first served basis. Same procedure is followed with regard to samples from other institution users

5. Maintenance of Sports and Games Facility

The sports equipment, fitness equipment, ground and various courts are supervised and maintained by the Physical Directress and Faculty members of Physical Education Department respectively. Extensive equipment in the Gymnasium are maintained. Ground level maintenance is done annually during vacation in addition to the seasonal maintenance

done once in every three months. Grounds men, vendors of Sports goods and students of Physical Education jointly maintain the sports equipment.

6. Maintenance of Campus Cleanliness

Cleaning of the campus areas including the academic and administrative buildings is performed daily in the morning before the regular classes begin with the help of housekeeping team. Toilets are cleaned thrice every day. The whole campus area is maintained by the housekeeping supervisor who will be reporting the completion of work to the Estate Manager.

7. Maintenance of other amenities

The effluent treatment plants and rain water harvesting systems are maintained by the Estate Manager and support staff. The maintenance of equipment for water pumping plants, sewage, elevators are undertaken as per their preventive maintenance schedules and guidelines by the equipment supplier. The campuses are equipped with 24/7 safe and adequate drinking water supply. Fire extinguishers are installed in various blocks and are maintained by the respective departments with the support of technicians. Amenities like canteen and juice shop, stationery, bank and ATM facilities, laundry and reprography accessible for all stakeholders are maintained by respective service providers on annual contract.

Green environmental aspects —Garden, the orchards, bird feeders, solar panels, wind mill, rainwater harvesting systems, and the green house are maintained by the gardeners every day and frequently by the National Service Scheme volunteers as a service activity.

8. Annual Stock Checking

Annual stock checking of furniture, lab equipment, stationery, ICT facilities, sports items and all assets and reporting of repairs is done by designated faculty as a year ending activity and the consolidated report is submitted to the administration to take up necessary actions if required.

9. Replacement of Equipment/ Electronics /Computers

The maintenance comprises actions that are carried out to replace worn out assets. To avoid e-waste, the outdated electronics /computers are put on buy back as per norms and new items are procured.

10. Day to Day Emergency Maintenance

Day to day maintenance includes daily running repairs, like replacing light bulbs, repairing water leakages, leaking water pipes, taps, valves and cisterns, cleaning blocked drains, repairing locks and door handles and other minor repairs that necessitate day to day maintenance checks are taken care of by the Manager and his team members.

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Problem Reported On: 29/10/20 Time : (1.00

Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
)	For problem	A7 lode G1.12-29,24	of im

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

Time:

DEPARTMENT OF CASALU

Problem Reported On: 31/10/2020

Problem Attended On:

Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1-	Tube lights are not working at spot room.	Exam Cell	OK Faire

Signature of Maintenance Incharge

Signature of Lab Incharge 5HOD ALTAM - Tekkali

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BS 60 H
Problem Reported On: 2:11.20
Time: 2:15

Problem Attended On: Time:

Action taken/Remarks

S.No.	Name of Work / Problem	Location
0	111	
	light.	
6		2006.
19/	Notwooking	RBOLCK GE
	for and light	Decree WE
	3 mayer	OT.
	2 - 3	(English Lab)

Signature of Maintenance Incharge

Signature of Eab Incharge/HOD Anne

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Problem Reported On:

GHI

Problem Attended On:

Time: 2/11/20. 10.45 Time: Name of Work / Problem . Location Action taken / Remarks Fan is not-1st floor Room 20 workin G2H I

Signature of Maintenance Incharge

M-Rolulu Signature of Lab Incharge/HOD

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 11/20 Cn. H I

S No Name of Work / Problem

Problem Attended On: Time:

Action taken / Remarks

Time: 10.30 Am

The second second	Name of Work/I Toblem	Location
	Fan is not working	19 Room 20-1st
		O1H 1
2,	Fan and light is	Room 47. 200
	not working.	COHI

3. Sim

Signature of Maintenance Incharge

M- Kalulu Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND ME JAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 5/11/20

Problem Reported On: Time: In an Am

GHI

Problem Attended On:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
	Light is not working	1st floor. Room -19	B. Niempo

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 6/4/20

Problem Reported On:

Time: 10-42 am. G1.H I

Problem Attended On:

Time:

146	S.No.	Name of Work/Problem	Location	Action taken / Remarks
_		Light is not coosing		
	8,	fan and light is	Room 44	OK
		form is not working	y Room 23	B. Nivayra

Signature of Maintenance Incharge

M. Rejulu Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

Time:

DEPARTMENT OF GHILLI

Problem Attended On:

Time:

S.No.	A CONTRACTOR OF THE PROPERTY O	Location	Action taken / Remarks
t	Fan Sound prob	em Room 28 GHI	
2	tight is not	Room 22, 17, 4, 18,30 GIHI	3 6
		18,30 分料工	O Sh
3	fan is not working	10, 14, 32, 41	N. 200
		07H2	

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

	Time:	0-30	Problem Attended On : Time :
S.No.	- water of Work/ Problem	Location	Action taken / Remarks
2.	RNO-HZ out side power con Main switch not working RNO-43 five pin Socket switch no working	1-BH-I 200+ RNO-42	Complet
ignatı	are of Maintenance Incharge		Signature of Lab Incharge/HOD

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF MBA Problem Reported On: 27/11/2020

Problem Attended On:

3.30 PM Time: Time: Action taken / Remarks Location S.No. Name of Work / Problem

Aditya Institute o

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI**

SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Jangement Koom

Problem Reported On: 9 30 ul 2020

Problem Attended On:

Time: Time: Action taken / Remarks Location S.No. Name of Work / Problem

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF IT

Problem Reported On: 01-12-2020 Time:

10-15 Am

Problem Attended On:

Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
0	Fans- 3 Nos	13"Bleck CFF-13)	
R)	electrial pipe samoge	"n' slock	0.8
	pay samuje	(Pr-03)	

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 53 - 12 - 2020 Time: 11- (T) OM

Problem Attended On:

	Time: U-00 Pt		Time :
S.No.	Name of Work / Problem	Location	Action taken / Remarks
10	sockets y switches	CBlock CP (ab First-floor FP-15	Dy.

Signature of Maintenance Incharge

Signature of Lab Incharge/ HOD editya Institute of Tachhology &

14

SERVICE CALL REPORT (COUNTER FOIL)

.No. Name of Work / Problem	Location	Action taken / Remarks
Fan is not exorking	Gitt I	
1 Locking	Room 44	
Dog. C.		, O. Cin
		Test, test

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: OF 13 0 45 H0 5 40-1 Problem Reported On: OF 13 0 45 H0 5 40-1 Time: S.No. Name of Work/Problem Location Action taken/Remarks I R.NO +8 + 400 + 18 LIGHTSNOT WORK BH T SOCKET Problem New Switch board required BH T Signature of Maintenance Incharge Signature of Lab Incharge HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 08 12 20 Problem Attended On: Time: S.No. Name of Work / Problem Location Action taken / Remarks TUBELIGHT IS NOT 25 and 32 RNO 39, 11944 RNO 25 and 32 RNO 39, 11944 RNO

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 9102120 Time: 10-60 Problem Attended On: Time: S.No. Name of Work/Problem Location Action taken/Remarks Signature of Maintenance Incharge Signature of Maintenance Incharge Signature of Maintenance Incharge

IENNALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 12/12/20

Time: 60.00 a	GH2	Problem Attended On :
No. Name of Work / Problem	Location	Action taken / Remarks
main problem by Light is not working.	Room-6 Gitt2 Ground floor at steps Gitt2	OO Mikalin

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

AUTITA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

15/12/20

GI-H

Problem Attended On:

Problem Reported On: Time: 10-00 am

Time: Name of Work / Problem Location Action taken / Remarks Light is not working. Room 21 GzH2 (2) Lightspare not Mess. Gitt 1 working. (Round

Signature of Majatenance Incharge

Signature of Lab Incharge/HOD 12/20

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 16/12/2020

Problem Attended On:

Time: 10:30 mg

S.No.	Name of Work / Problem	Location	Action taken / Remarks
	Fan Not worky	\$6-26	- []
2'	2. Tublishts	FF-14-0	Dans
3-	took bothis		70

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD Dept. of ECE Aditys Institute

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOStal-I and III Problem Reported On: 1612/20 Problem Probl Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
4	RNO.18 NO TUBE light-BH-I RNO.18 TUBELIGH is not working—	BH-I R·NO-10 R·NO-10	Completed

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Problem Reported On:

17/12/20

S.No.	Name of Work / Problem		Problem Attended On : Time :
b	Light is not working.	Room-26- GiH 2	Action taken / Remarks
6	Light is not	1st floor wash-	er Fayla
	Working.	800m.	

ignature of Maintenance Incharge

M. Rajulu 17/12/20

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYSHOSHA-3

Problem Reported On: 18/12/20 Problem Attended Counter Time: 10-30

Problem Attended On:

S.No. Name of Work/Problem	Location	Agtion to La 15
R-NO-10 Maly Switch board loose & Holder is not working	RW0-10 BH-W	Action taken/Remarks Complete Guy

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAI- TI

		Time:	8 12 20	I II		
	S.No.		10-30		Problem Attended On :	
	1	10. 1.		ocation	Time:	
	2.	fan is not u Tube light is a working and	JOSKY - B	100.9 BH	Action taken / Remarks	
		Working 130	net (No light) //	- Ital	-
	- 1	Taking Sound	tayis o min	1 -	Completed	
1	3. [Tube light is working and beking sound	1 1 100.	4 34-24	6	
L	M	Down 18 & 9 Uberights and Wording No. 30 No. 918 of Maintenance Inchar	endor 18	21 21	(July	
6	1. R	No 30 No 9:00		1/54		
Sign	hature	of Maintenance Inchar	W- 30,	BH-Z		
			ge			
					Signature of Lab Incharge/HOD	
					X	

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 9 4 1/2 2 0

Problem Attended On:

S.No.	Name of Work / Problem	Location	Time : Action taken / Remarks
(1)	Sacket	SF-09	, and taken the marks
		3 / - 6 9	
	, No + Warlang	C-Duile	Charles
	×		William
- 1			
			0 1/

Signature of Maintenance Incharge

Signature of Lab incharge / HOD Management, TEKKALI

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On:

Gr. H. 2.

No. Name of Work / Problem	0 am 19-12-28	Time:
fan is not	Room 36.	Action taken / Remarks
working:	First floor-GHZ	Pr
		O Knikatilu
	-	

nature of Maintenance Incharge

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF ECE

Problem Reported On: 02/01/2021

Problem Attended On:

S.No.	Name of Work	The second secon	Location	Time : Action taken / Remarks
1.	wite Ex	lence	ECE office	
				0 14
				N.

Signature of Maintenance Incharge

Signature of Lab incharge / HOD Dept of ECE

Adires Institute

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF (0) Block CSE Dept Problem Reported On: 05 |01 21 Problem

Time: 10:00 A.m

Problem Attended On:

S.No.	Name of Work / Problem		riffle,
4	Computers(3)	Location	Action taken / Remarks
	power boards not working	FF-16, Advanced programming Lab, D-Block	of wh
	Tube light not working		NO

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 71.2021 Time: 10.00 Problem Attended On: Time: S.No. Name of Work/Problem Location Action taken / Remarks B.S.H HOD ROOM.NO Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** APSSDC Problem Reported On: Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks BLOCK - F' Blow APSSDC Ond Play Signature of Maintenance Incharge Signature of Lab Incharge / HOD APSSDC - ALTAM ADITYA INSTITUTE OF TECHNOLOGY TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: Problem Attended On: Time: 10-00 Am. Time Name of Work / Problem Action taken / Remarks ight is not working room. 45 GHI 700m-25 GHT OCC 25 Light a not

Signature of Maurienance Incharge

Signature of Lab Incharge HODF112

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTEL- III.

Problem Reported On: 7 1/21

Problem Attended On:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1	R-13		
	BH-10	tube light	- 61/
		is not working	
			1 Suy
			S 1)

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 18/11/2)

Problem Reported On:

Problem Attended On:

	Time: 11-40 a	m G7H	Problem Attended On : Time :
S.No.	Name of Work / Problem	Location	Action taken / Remarks
(l)	Light is not working	R00m-24 67H1	L'Ading Candong.

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL 3 Problem Reported On: 19 11 21 Problem Attended On: 10.30 Time: S.No. Name of Work/Problem Location Action taken / Remarks rize 3 pin Signature of Maintenance Incharge Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTAL-TI Problem Reported On: 20 1121

Problem Attended On:

S.No.	Name of Work / Problem		Problem Attended On:
1.1	R.NO-34 Plug	Location	Action taken / Remarks
	514.00	BH-2	
-	Shocket dange	BH-2 R-NO-34	00
		2100 39	
			é
-	STATE OF THE PARTY		Lowy
	SPIRAL STATES		Coluny

gnature of Maintenance Incharge

Signature of Lab Incharge/HOD

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTAL-I

Problem Reported On: 210121 Time:

Problem Attended On:

Time:

S.No	. Name of Work / Problem	Location	Action taken / Remarks
1-	RNO20 fanis	R.NO-20	Complet

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

- Laiv

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF CSE

Problem Reported On: 20-1-2021

Problem Attended On:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
d,	Not supply electric pover	D. Block FF-10 class Room	De S. Rambales

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD Teldtall-532 201, (A.P.)

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Problem Reported On: 22/01/2021 Time: 10-10Am

Problem Attended On: Time: 10 -

S.No.	or work/ i Toblelli	Location	Action taken / Remarks
0	Tube lightnot	#FF04/	100
		The second secon	
B	Sink vost unking		
2	n e		Head of the Repartment

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 22-01-2)

Problem Attended On :

(0:30	Problem Attended On:
roblem Location	Time :
witch C-Block SF-83.	Action taken / Remarks
witches c-reloca	The state of the s
C-DYMGYCHMAN	10-1
Noken c-trlown	340
Simulation 66	Day of the discass
	witch C-Block SF-83, witches C-Rlock

Signature of Maintenance Incharge

Signature of Lab lacharge / HOD menant, TERRALI

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEN TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL-2 and 3 Problem Reported On: 27 Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks Kingwater BH-2 Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAIT 2 Problem Reported On: 2 Problem Attended On: Time: Time: Name of Work / Problem Location Action taken / Remarks RNO.62

Signature of Lab Incharge/HOD

Signature of Maintenance Incharge

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 27/11/21

Problem Reported On:

Time: 10.00 am. G.H.

Problem Attended On:

Time:

S.No. Name o	fWork/Problem	Location	Action taken / Remarks
u. Fan i	s not working.	Gitt 2 Room and floor, 46	B. Meour

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

ECC

Problem Reported On : 12/1/21

Problem Attended On:

Time: 2:00 PM

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1.	Fan's Not working	SF-21 (17	06
		SF-26 (1)	04
			Dor.

nature of Maintenance Incharge

Signature of Lab Incharge / HOD

Dept of ECE Adire Tactions

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMEN TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL I and III Problem Reported On: 28/1/21 Problem Attended On: Time: Time: 10-30 S.No. Name of Work / Problem Action taken / Remarks Location 2.00. 69 famis Signature of Maintenance Incharge Signature of Lab Incharge / HOD

57

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 28 1 2-1

Problem Attended On:

Time: 10.00 A

Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1-	Ceiling Farm	C-Block SF-03	d
			Bead of the Managerman

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

Management, TEKKALI.

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF B. SELT Problem Reported On: Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks Tube light

Signature of Maintenance Incharge

Head Bas Signature of Lab Incharge / HOD And Menagement Tekscall 532 201

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI**

SERVICE CALL REPORT (COUNTER FOIL)

Problem Reported On: 29/12/ LIBRARY **DEPARTMENT OF**

Problem Attended On:

Time: 9 45

S.No.	Name of Work / Problem	Location	Action taken / Remarks
2/3.	Fan Degreel Juste Coglus - 2 Swetch	Le. Essay	pole Solut

Signature of Maintenance Incharge

TRULUGY AND MANAGE TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS Hostal I and II Problem Attended On: Time: S.No. Name of Work / Problem Location Action taken / Remarks BH-I Hostel Gale Out side light not RNO. 23 Plug shocket _ BH-2 is not working R.NO - 23 R-NO-23 RNO-25 Tubeligna -- BH-2 is not working (nolight) R.100.25 Signature of Maintenance Incharge Signature of Lab Incharge/HOD AUTITA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: 30/1/21 Time: Problem Attended On: S.No. Name of Work/Problem Time: Action taken / Remarks Signature of Maintenance Incharge Signature of Lab Incharge/HOD TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: Problem Attended On: 30/01/21 11:00 Time: Name of Work / Problem Action taken / Remarks Location S.No. Signature of Lab Incharge/HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF Loreny Problem Attended On: Problem Reported On: 19/02/21 Time Time: Action taken / Remarks Name of Work / Problem Location Teek lights Signature di Lai incharge HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On: Time: Action taken / Remarks Location Name of Work / Problem S.No. Wo, Intercom D-Block HOD OSFICE Adity a Instruction of Signature of Lab Incharge/HOD Signature of Maintenance Incharge Tekkall-\$32 201, (A.P.) ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 1912121 Time: 10-30 Problem Attended On: Time: Action taken / Remarks Name of Work / Problem Location four is not working - RNO. 72 (BH-I) four is not working - RNO-14 (BH-I NO Light (Tube) - RNO-14 (BH-I Signature of Maintenance Incharge Signature of Lab Incharge / HOD

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: 02 02 21 Time: 4100 pm Problem Attended On : Time :

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1	Tube light not	D-Block,	
	Tube light not working	CSE Dept.	ala al
2.	Computers	FF-16.	OLD
	switch board	Advanced	
	not working so - 4	programming	Marian

Signature of Maintenance Incharge

Technology & Managemen Signature of Lab Lychalles 32201, (A.P.)

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BS E(H Problem Reported On: 04.02,2021

Time: II A.M

Problem Attended On : Time :

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1.	Teube light (reiling) is not working	18' BLOCK English Lab-61.F-07	av .
2.	A/c is not working		OF
			maken y-narrow

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 2/2/21 Problem Attended On:

Problem Reported On:

Time: 10:35

Gr H

Problem Attended On:

Time:

	Time: 10 33		Action taken / Remarks
S.No	Name of Work/Problem	Location	
(1,	Fan is not working	Room-8 Colt 2	06
1 3	Mess-Cooking shed fan all bolts are	211. 2000	06
	fan all bolts are		B. Nirupa
1			M-Rasulu.

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL I and I Problem Reported On: 17/2/21 Problem Attended On: Time: Time: 10.30 S.No. Name of Work/Problem Location Action taken / Remarks fam is not _ RNO 33 BH-I yorking Balkroom switch R.No.7 BH-2 Board 100se Barcony & com - R. No. 8 BH. 2 Steps Corner Round -Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF G.H Problem Attended On: Problem Reported On: 18/2/21 Time: Time: 10 40 am. Action taken / Remarks Name of Work / Problem Room -3 Gitt an is not working Room - 47 Gitt 2 Signature of Lab Incharge HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTALI Problem Reported On: 18121 Problem Attended On: Time: Name of Work / Problem S.No. Location Action taken / Remarks switch not working (Direct) R-NO-18 NO Tube light and stand loose R-no

Signature of Maintenance Incharge

34

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL-I Problem Reported On: 20/2/21 Problem Attended On: Time: 10.30 S.No. Name of Work/Problem Location Action taken / Remarks 12.00.52 NO TUBE - RIND 52 BHT light 2 five Pin sockett - RNO. 62 BH-I 1005e R.NO. 62 Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: Problem Attended On: 22/02/21 Time: Name of Work / Problem Action taken / Remarks Fan Oil leakaged - R-72 BH-II R-35 - Plugshocket - BH-I R-TV-1 Fan is not working - BH-I Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) ELD **DEPARTMENT OF** Problem Reported On: 24/2/2 Problem Attended On: Time: 10.0000 Time: Action taken / Remarks Name of Work / Problem Location Boad of the Department Signature of Lab Incharge / HOD Signature of Maintenance Incharge Altya Institute of Technology,

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Gr. H Problem Reported On: Problem Attended On: Time: 10.00 am. 27/2/21 Time: Name of Work / Problem S.No. Location Action taken / Remarks NO 3 pin plug point- Room - 30 G1H2 NO 3 pin plug point Room-16 Git1 B. Niver no 3 pin plug point Room - 39 (74) (6×12 Signature of Lab Incharge HOD Signature of Maintenance Incharge DITYA INSTITUTE OF TECHNOLOGY AND MANA TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: 2-2021 Problem Attended On: Time: Time: S.No. Name of Work/Problem Location Action taken / Remarks

S. Rambas Head, Dept of CSh Signature of Maintenance Incharge Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Attended On: Problem Reported On: 102/21 Time: Time: Action taken / Remarks Location Name of Work / Problem S.No. R-33 Bath room holder Set loose and bedlight holder damage R-31 Fay is not working Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: Problem Attended On: Time: 16/02/21 Time: S.No. Name of Work/Problem Location Action taken / Remarks Enterance light not ture of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 16 2 Problem Attended On: Time: Time: Name of Work/Problem Location Action taken / Remarks

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** BOYS HOSTEL- Problem Attended On: Problem Reported On: Time: 05/02/21 Action taken / Remarks Name of Work / Problem Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL-I Problem Reported On: 06121 Problem Attended On: Time: 10-30 Time: S.No. Name of Work/Problem Location Action taken / Remarks RINO. 41 tan is RNO.41 tanis R.No.41 Making sound BH-T Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL I and I Problem Reported On: 08/2/21 Time: 08/2/21 Problem Attended On: Time: Name of Work / Problem S.No. Location Action taken / Remarks R.100-41 Rino 41 fanis not working TBH-I RNO 22 famis BH-2 NOT WORKING RNO-(22) Signature of Maintenance Incharge Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF GOLD Problem Reported On: Problem Attended On Time 10 50 am. 25 2 21 Time Name of Work / Problem Action taken / Remarks Fan is not working Room- is Gattl 2 No 3 pin plug point Room-16 (7H) 3, NO. 3 pin plug point Room - 28 GTH) Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF ECE Problem Reported On: 26/02/2021 Problem Attended On : Time: 9:30 Pm Time: S.No. Name of Work / Problem Action taken / Remarks 11. Fay not working "A"- SF-15, 16 SF 12, SF-09 (Stoff) SF 2. Light problem SF-15 010 Signature of Maintenance Incharge DITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE (D'Block) Problem Reported On: 26/02/2021 Problem Attended On: Time: OSCORM Time: S.No. Name of Work / Problem Location Action taken / Remarks Two tube lights LANDLING NOT K.V.C.H.Char Signature of Maintenance Incharge Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMEN SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BS Q H Problem Reported On: 04.02.2021 Time: 11 A M Problem Attended On: Time: S.No. Name of Work / Problem Location Action taken / Remarks A/c is not working. English Lab. F.F-09 Provide Pesticides to Prevent - Pests Repair Wheel Chairs fure of Maintenance Incharge Signature of Kab Incharge / HOD H lukkalissaz 201 Adity ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** Problem Reported On: 4-2-2021 Problem Attended On: Time: 10:15 8m Time: S.No. Name of Work / Problem Location Action taken / Remarks HOD ROOM FF 08 Signature of Maintepance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) 5/2/21 **DEPARTMENT OF** Time: 10-45 am. Gr.H. Problem Attended On: Problem Reported On: Time: Name of Work / Problem Location Action taken / Remarks S.No. changing plug problem. Room. 32 Gitt 2, 5 pin plug not working. Room. 9. Gitt 2 and bulb holler broken 2 Tube lights avend Reception GIHZ working. M. Kejulu Signature of Lab Incharge/

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF E.C.E Problem Reported On (4) FOUY TUBE Light & problem Attended On: failed Time: 014.2021 Time: Name of Work / Problem Action taken / Remarks Location S.No Four tube-lights Acloc Meximes D. T Signature of Lab Incharge / HOD Signature of Maintenance Incharge 1/2/2021 ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL Problem Attended On: 102/21 10:00 Arm Time: Problem Reported On Action taken / Remarks Location Name of Work / Problem S.No. 5 tube light is not working Fan's notworking Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) Problem Attended On: 1/2/21 DEPARTMENT OF Time: Grilt Problem Reported On: 10-30 am Action taken / Remarks Hoor. 1 Door locked O 6 Time Location Name of Work / Problem Room - 57 Gitt 2 2nd 5.No. J. Fan sound. 25 Fan not working. Room-8. GHZ Bround Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE Problem Attended On: Time: H. 00 Am 12:00 Am) Problem Reported On: Time: Action taken / Remarks Location Name of Work / Problem S.No. 2 Tube light net working (chocke) 2 Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL - I Problem Reported On: 14 21 Problem Attended On: Time: 10-30 Time: Action taken / Remarks Name of Work / Problem Location S.No. Light with R.NO-08 frame (stand) BH-I Require (Two light) Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks Signature of Maintenance Incharge Signature of Lab Inc arge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BSAV Problem Reported On:

24/2/21

Problem Attended On: Time:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1	perbe behr	A-Block A-Block	00

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

DEPARTMENT OF BOYS HOSTAL- I & III

Problem Reported On: 24/2/21
Time: 10-30

Problem Attended On:

Time:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
4	R-No-30 fan is _	BH-I.RNO-30	
2	Common bally room	- BHI GIF	100
	required Baltimon	BH-III RNO-	Complete
3/	required R. No. 31 Baltroom he identity working	8	lang

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTAL-2 Problem Reported On: 25/2/21

Time: 1A-31

Problem Attended On:

Time:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1-	R.NO. 62 tour is Running Slow	- BH-2 200-6 (SIF)	n10
	Running 51000	K-100 02 (31)	C
			July 1

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Gi.H Problem Attended On: Problem Reported On: 26/2/21 Time: Time: 12.00 am. Action taken / Remarks Location Name of Work/Problem Room: 16 Gr. H Fan is not 11 M. Kojulu 26/124 Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Attended On: Time: 26/2/21 11:45 Am Time: S.No. Name of Work/Problem Location Action taken / Remarks Signature of Maintenance Incharge Signature of Lab Incharge/ HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL-I and III Problem Reported On: 27/2121 Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks R-NO-61 BH-T NO 68 famis - RNO-68, BH-1 NUTUBE ligh an Regulator Signature of Maintenance Incharge Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL Problem Reported On: Problem Attended On: Action taken / Remarks Name of Work / Problem R-43 Plugshocket Switch is not working R-64 Carrider tubus light is not working Signature of Lab Latharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYSHOSTAL 2 Problem Reported On 0112121 Problem Attended On: Time: Action taken / Remarks Name of Work / Problem tan is not _ R.NO-36 BH- 2 gnature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Land II Problem Attended On 02 02 21 Time. Name of Work / Problem S.No. R-80 Switch damage and socket loose R-52 Fan Running Slavano tabelight not working R-10 Fan is not working Signature of Lab Incharge / HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 06/3/21 Pro Problem Attended On: Time: Action taken / Remarks Location Name of Work / Problem BH-2, R.NO. 29 R.No. 29 fan is making sound RNO48 fanis BH-2 R-NO-48 Making sound BH-3, R-NO: 36 RNO: 36 famis stow BH-3 Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL I, II, III Problem Attended On: 08/3/24 Problem Reported On: Time: Time: Action taken / Remarks Name of Work/Problem Location S.No. Faus Marking_R.NO. 48, 54 BHI Sound. 48, 54 fours Running slow R. NO. 49, 55 BHS 3. fay is not working - RNO. HI -BH-2 CANTO CHARLESTON CONTROL CONTROL fan is not working 200-32, BH-3 Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF 13,045 HOSTAL -I Problem Attended On: Problem Reported On: 09 3 2 Time: Time: Action taken / Remarks Name of Work/Problem Location S.No. R.NO. 22 five 10 Pin socket, and oose, and Two switches are not working water cooler 2. Signature of Lab Incharge / HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** Problem Reported On: 15-03-2021 Time: 11-45 AM Problem Attended On: Time: S.No. Name of Work / Problem Action taken / Remarks Location Signature of Maintenance Incharge PRINCIPAT Sighapure natiante on inger mortogy & Management ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL Problem Reported On: 15/3/21 Problem Attended On: Time: 10-30 Time: S.No. Name of Work/Problem Location Action taken / Remarks fan is not BH-21-65RM working R-NO-65 RNO.47 tanis Making sound making sound amend working Mess Two water Coolers are Elect Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF EEE Problem Reported On: |9-03-202| Problem Attended On: Time: 3:0000 Time: Action taken / Remarks Name of Work / Problem Location S.No. Fanslow nunning GF-10 (05 No)

ignature of Maintenance Incharge

47

Signature of Lab Incharge /410

n.O. Dores

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** Problem Attended On: Problem Reported On: 217 Time: 06-02-21 Time: Action taken / Remarks Name of Work / Problem S.No.

nature of Maintenance Incharge

b Incharge/HOD Signature Adityon

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On:

Time: 10.30 am.

6/3/21

Gr. H Problem Attended On:

Time:

S.No. N	ame of Work / Problem	Location	Action taken / Remarks	_
1 F	an is not working	ng . Room -26-GH2	Co Ju	
2 F	un is not working	Mess.	ole produ	

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On:

Time: 10:30 am.

2/3/21

Problem Attended On: Time:

-	Name of Work / Problem	Location	Action taken / Remarks
	Fan Sound problem		00
2	Fan sound problem	Room 50 GHZ	
3	Fan Sound problem	Room 43 ChH2	OU ROSE
4	No 3 pin plug point	Room 25 GiHI	O PC

1 and Signature of Maintenance Incharge

Signature of Lab Incharge HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL I and II Problem Reported On: 01/3/2/ Time: Problem Attended On: 10-30 Action taken / Remarks Name of Work / Problem Location RN0-78 RNO 78 famis. BH-2 Not working 2. e.no. 10 fair is - BH-2 R-NO-10 Running Stow BH2 RNO. 65 RNO.65 fanisfive pin switch - R.NO. 27. BHI Signature of Lab Incharge / HOD Signature of Maintenance Incharge **ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT** TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF G (D) Block) Problem Attended On: Problem Reported On: Time: 10:00 A.M Time: S.No. Name of Work / Problem Location Action taken / Remarks Signature of Lab Incharge/HOD Signature of Maintenance Incharge Aditys Institut Technology & ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 03.03-21 Problem Attended On: Time: 2.30 P.M Time: S.No. Name of Work/Problem Location Action taken / Remarks Signature of Maintenance Incharge Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL-3 (MCSS) Problem Reported On: OH 13 2 Problem Attended On Time: Time: 10-30 Action taken / Remarks Name of Work / Problem Location S.No. Mess water mess coolers are not (not cooling) Signature of Maintenance Incharge Signature of Lab Incharge/HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: OH 3 2 Problem Problem Attended On Time: Time: 10-30 Action taken / Remarks Location S.No. Name of Work / Problem Two fan are not working Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE Problem Attended On: Problem Reported On: 6-03-2021 Time: 10:00 / M Action taken / Remarks Location Name of Work / Problem S.No. Ac fan imot working, due to that coal air not coming. e of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF ECE Problem Attended On: Problem Reported On: 12 3 /2 Time Time: 11 4,00 Action taken / Remarks Name of Work / Problem Location Kan Sound -Signature of Maint Signature of better bergs ARICH

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF ECE

Problem Reported On: 12/3/1 Time: 11 . 00

Problem Attended On

Time

Department of ECE

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1-	Switch Board Saket problem	S.F-033	06
2.	Dan Slaw -	SP-34	00
	Capacites pross)		D. J.

Signature of Maintenance Incharge

Department of ECE se of Technology

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL — I Problem Attended Counter Problem Reported On: 1213121

Problem Attended On Time

S.No. Name of Work/Problem	Location	Action taken / Remarks
3 Con Punior	-BH-2, R.NO. 29 -BH-3, R.NO. 22 -BH-3, R.NO. 22 -BH-I R.NO. 48	

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF BOYS HOSPAL TELL Problem Attended On: Problem Reported On: 23 3 21 Time: Time: 10:30 Action taken / Remarks Location Name of Work/Problem S.No. RNO.12 SOCKet 00 RH-I Major Gate Near P. 55 (LED) Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** Problem Reported On: 2 4 03 2 Problem Attended On: Time: 2:00 PM Time: Action taken / Remarks Name of Work / Problem S.No TUBELISH NOT 5 P.D.C 2015 TUBELISH NOT SIF-18 rusofan's not walcing 5.5-18 Tube light werking Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Gn. H. Problem Reported On: Problem Attended On: 25/3/21 Time: 10-00 am. Time: S.No. Name of Work / Problem Location Action taken / Remarks Fan is moving Room 31 GH1 1200m 44 Fan is moving Slowly Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Gill 20/3/21 Problem Reported On: Time: 10:30 Am Time: Action taken / Remarks Name of Work / Problem Location fan is not Room-44 M Foulu 20/3/2y Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL - I and I Problem Attended On: Problem Reported On: 20/3/21 Time: Time: Action taken / Remarks Name of Work / Problem S.No. Location BH-2 R.NO. 52 RNO.52 SOCKet (FIF) 100se · CFIF) BH-2 GIF. Tube light + BH-3 (GIF) not working Mess outside These wash mess outside water coolers - mess (1) NOT GOOTING BH.3 (first flow) Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: Problem Attended On:

No.	Name of Work/Problem	Location	Action taken / Remarks
di	Fan is not working	Room 49 - GHZ	00
2	I take is not comeking	Room 3. Gitz	OD nikaju
3	Goround floor Corner	GHZ at Room 19	Obe his

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF BOYS HOSTEL- I and I Problem Attended On: Problem Reported On: 27 8 4 Time: 10-20 Time: Action taken / Remarks Location Name of Work / Problem S.No. SIF Baltyoom 00 light is not working RED LIGHT IS Not working wear wit (and Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF 3015 Hosfel - 2 Problem Reported On: 2713121 Problem Attended On: Time: Time: 10.30 Action taken / Remarks Location Name of Work / Problem S.No. R. NO. 42 favi BH. 2 Q.NO.42 (NOT WOOKING) 2. No. 45 fan is NOT MOLIKING RH-3 R. NO. 06 fam ise Lear, tog. Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE Problem Reported On: 29/3/21 Time: 3:00 PM D Block Problem Attended On: Time: Action taken / Remarks Location Name of Work / Problem S.No. Bristrowton their D Block Intercom Phone Nut r.v.c. Nerch worling. HOD, STN ROOM F-14 Signature of Maintepance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF 29/3/21 Problem Attended On: Problem Reported On: Time: 10-20 am - G7 H Time: Action taken / Remarks Name of Work / Problem Location Fan is moving slavy: Room 31 - Gitt I 2) Fan is moving story Room. 44 Room 18 Cott II 3, Fan is moving slowly and make, Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On: Problem Attended On: 30 3 21 Time: Time: S.No. Name of Work / Problem Action taken / Remarks R-25 Pay Sound problem R-62 Fan Nut bolet Loose R- 66 tube light not working R = 62 Fay is running Slow - 65 Fay not working Signature of Maintenance Incharge Signature of Lab Detarge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEI - I Problem Reported On: 31/3/21 Problem Attended On: Time: 10-30 Time: Name of Work / Problem Location Action taken / Remarks D/NO.12 Light_BH-I is not working R. NO. 12

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 17 Problem Reported On: 1 -3 -2021 Time: 9:31

Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1-	Switch board Problem	B-block (FF-13) ItJab-2	-ol

James Signature of Maintenance Incharge Head of the Ochartment Signature of the Incharge/HOD Aditya lostitute of

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Poly rednic

Problem Reported On: 01 03 2021

Problem Attended On:

Time:

	Time:		Time:
S.No.	Name of Work / Problem	Location	Action taken / Remarks
1	Tube light, faur	Diplome Office 15/ SF/11	D. love for more per own

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD Polytechnic

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF ECE

Problem Reported On: 1-03-202)

Problem Attended On:

Time: Time: 10:30 An

	Tillio :	Location	Action taken / Remarks
S.No.	Name of Work / Problem	Location	
1.	Fan'y not	SF-21	OK
	working -	A ()	06
	1. Pan - Not worky 2. Pan - Sound	Evanily Session	Borc
	27-1-300-6	Proce)	D. July Hoperson (HOD)

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Boys Hostel- I Problem Reported On: 05/4/21 Problem Attended On: Time: Action taken / Remarks S.No. Name of Work / Problem Location 1. Near R NO. 77 ComidW LED (Round) light is not working Signature of Maintenance Incharge Signature of Lab Incharger HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On: Hyl2021 Time: 10:25 Am Time: Action taken / Remarks S.No. Name of Work / Problem Location Both annot-Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL- I and III Problem Reported On: 07/H/2/ Time: 10-00 Problem Attend Time: Problem Attended On: Action taken / Remarks Location Name of Work / Problem ignt is not four is Running R.NO.08, BH Slow Signature of Lab Inc Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: G1 H 3/4/21 Problem Attended On Time Name of Work / Problem Location Action taken / Remarks Fan 15 not Working 100 m - 43 GHT is not working Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOY'S HOSTEL-Problem Reported On: 03 4 21 Problem Attended On: Time: Time: Name of Work / Problem Location Action taken / Remarks BH-I R-NO-04 Signature of Maintenance Incharge Signature of Lab Incharge/HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: Problem Attended On: Time: 10.30 am 5/4/21 Time: Name of Work / Problem Location Action taken / Remarks Room 15 GHI Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: 2T (01/4/2021) Problem Attended On: Time: 01: 8 L pm S.No. Name of Work/Problem Location Action taken/Remarks I. AC Window 94-10 Repoir Net (ab Pagaday)

Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Polytechnic (Piploma)

Problem Reported On: 01 04 2021

Problem Attended On:

	Time:		Time:	
S.No.	Name of Work / Problem	Location	Action taken / Remarks	
1	A.C. Not wolking	SF-12 (Dy. sirector	00/	
2	Switch Board for (Zerox Macline)	St.11 (ottice horm)	Deam on-	

Signature of Maintenance Incharge

Alle Color

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Training of Policies

Problem Reported On :

luizery 1


Problem Attended On:

S.No. Name of Work / Problem	Location	Action taken / Remarks
1) Y AC'S NOT NOTKING	Parihitli les	Carlo 1
NPUKING .	(D- Block	

Signature of Maintenance Incharge

Signature of Lab Incharge HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BCB Problem Reported On: 1141204 Problem Attended On Time Time: 11: to AM Action taken / Remarks Location Name of Work / Problem S.No. D. Signature of Lab Incharge HDD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Attended On: Problem Reported On: 01 04 2021 Time Time: Action taken / Remarks Location Name of Work / Problem Fan making sound Signature of Lab In harge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) G.H. 2/4/2 Problem Attended On: DEPARTMENT OF Problem Reported On: Time: 11.40 am Action taken / Remarks Location Name of Work / Problem Roomug. GIHI Signature of Maintenance Incharge



ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF 9-4-2021 Problem Attended Problem Attended On: Problem Reported On: 9-4-2 Time: Action taken / Remarks Name of Work / Problem Signature of Maintenance Incharge 7842436373 Signature of Lab Incharge/HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOXS HOSTEL - 3 Problem Reported On: 09[4] 2 Problem Attended On: Time: Time: Action taken / Remarks Name of Work / Problem 1. Tube light is not work in Signature of Lab Incharge / HOD nature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL-Problem Attended On: Problem Reported On: 15 H 2 Time: Time: Action taken / Remarks ocation Name of Work / Problem S.No. teur is not RNO / MONKING four wing bred working Signature of Lab Incharge HOD gnature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE Problem Reported On: 22/06/91 Problem Attended On: Time: Time: S.No. Name of Work / Problem Location Action taken / Remarks Tube wights Data Amorphic - 2 NO'S Power sockers fary) Gor Signature of Maintenance Incharge Signature of Lab Incharge to states in seri ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) **DEPARTMENT OF** Problem Reported On: 14-06-21 Problem Attended On: Time: 9.00 00 Time: Action taken / Remarks Name of Work / Problem Location S.No. polled Soly Signature of Lat Signature of Maintenance Incharge

	SERVICE	E CALL REPORT (COUNTER FOIL)	
D	EPARTMENT OF	Exam cell.		
Probler	n Reported On:	20/06/21	Problem Attended On : Time :	
S.No.	Name of Work / Proble		Action taken / Remarks	
1.	Fiseina a	v Bramce	N. Comments of the second of t	
	Tubeliant	-		
	Fiseing or Tubelight Own the of Drangen Of CE.	eatil.		
	Frangen	2021	(A)	
	OF CE		000	
	Vame	* /	N. Criethabl	
			THOSE THOSE	
» ADI		OF TECHNOLO	Signature of Lab Incharge HOD OGY AND MANAGEMENT	
DEPA	SERVICE ORTHENT OF	TEKKALI CALL REPORT (C	GY AND MANAGEMENT	
DEPA Problem	SERVICE ORTMENT OF	TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On:	
DEPA Problem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TECHNOLO TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TECHNOLO TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE ORTMENT OF Reported On: 10:00 A Time: 7 25	TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
EPA oblem	SERVICE OR TIMENT OF Reported On: 10:00 A Time: John Work/Problem	TECHNOLO TEKKALI CALL REPORT (C	OGY AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks	
DEPA Problem	SERVICE OR REPORTED TO 10:00 A Time: I DE Name of Work/Problem	TEKKALI CALL REPORT (C	OF AND MANAGEMENT COUNTER FOIL) Problem Attended On: Time: Action taken / Remarks OF Confidence of the counter of the count	

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE ('D' Block) Problem Reported On: 9 11 2020 Problem Attended On: Time 9:30 A.M Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1	Drinking water TOP Problam -1 Drinking wate Ripes Problam-2	'D' Block Second Fools	S. Dombally

(aus Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

Head, Dest of CSL

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF CSe(D' Block)
Problem Reported On: 20/11/20

Problem Attended On:

	10.00 P	117	
S.No.	Name of Work / Problem	Location	Action taken / Remarks
1)	Driphing weter pipe ? Breakejes	SF	skomloby.
Signa	ture of Maintenance Incharge		Aditya institute of Sechnodray ucharga 440b Tekkali-532 201, (A.P.)

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On: Time: 11-00 am 67 H 2 Time: Action taken / Remarks Location Name of Work / Problem S.No. Co.H 2 glass broken B. Nixur water leak. Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CSE (D'Block) Problem Reported On: 241 112020 Problem Attended On: Time: Time 10:00 A.M Name of Work / Problem Location Action taken / Remarks S.No. Drinking water? Ripe Brinking P Aditya Institute of Signature of Lab Incharge / HOD meni Signature of Maintenance Incharge Tekkali-532 201, (A.P.)

-ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF IT Problem Attended On: Problem Reported On: 01-12-2070 Time: 10-15 Am Time: Action taken / Remarks Name of Work / Problem water leavage 'p" plack 0 in the staff Loon Waterlankage 9 Distange water Care Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF BOTS HOSAU TILL Problem Attended Time: Problem Attended On: Action taken / Remarks Location Name of Work/Problem S.No. VIP DINING HALL BH-3 Tap leakage 2- R-NO-01 2000 Land Tap leakage BH-3 3 R.NO. 64 Tap 15 - R.NO. 64 Broken BH-) Signature of Lab Incharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAU - III Problem Reported On: 07 12 20 Time: t0-00 Problem Attended On: Time: Action taken / Remarks Location Name of Work/Problem S.No. rook is condered RNO.21 Balt your tapis broken Q.NO. 21 Signature of Lab Incharge/HOD ture of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTAI - I and II Problem Reported On: 28/12/20 Prob

Problem Attended On: Time:

	-		
Time:	10-	30	

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1.	Attached bath	R.NO. 61 (stf)	Solver
2.	room tap wose	- BH-I (9H)	

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF 30/12/20-

Problem Reported On:

Time: 10-00 am.

GiH.

Problem Attended On:

Time:

S.No.		Location	Action taken / Remarks
(1)	Solar System	GIHI.	
3,	Solar System problem. Hot water tap is broken. Tap leak	GHI 1st floor.	M. Rogulustizo

ignature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOG	Y AND MANAGEMENT
SERVICE CALL REPORT (CC	
DEPARTMENT OF	
Problem Reported On: AJ SSD Time: 11-15-000	Problem Attended On : Time :
S.No. Name of Work/Problem Location	Action taken/Remarks
of alogo	
Second Flow Power Liter	
Second Flow Lows Lider Cay's Least Room Lider Least problem.	
2-97	
Pul fol problem.	NW NW
Signature of Maintenance Incharge	Signature of Lab Incharge (HOD
	OV AND WANAGEMENT
ADITYA INSTITUTE OF TECHNOLO	GY AND MANAGEMENT
CERVICE CALL REPORT (C	COUNTER FOIL)
DEPARTMENT OF BOYS HOSTAL- Problem Reported On: 21/12/20	Problem Attended On :
Problem Reported On 211121	Action taken / Remarks
S.No. Name of Work / Problem Location	Action taken/ Action
1. Wash basin - BH-I	9/2
pipe leakage	A CONTRACTOR OF THE PROPERTY O
	Ry
43	Signature of Late Incharge / HOD
Signature of Maintenance Incharge	
ADITYA INSTITUTE OF TECHNOLO	GY AND MANAGEMENT
SERVICE CALL REPORT (COUNTER FOIL)
SERVICE CALL REPORT	Problem Attended On:
DEPARTMENT OF BOYS HOSTAL-III. Problem Reported On: 2-3 12 12 12 12 12 12 12 12 12 12 12 12 12	Time:
- tion	Action taken / Remarks
Name of Work / Problem	President Countreles
1. R.NO-16 Plus BH-MI Tourk problem RNO-16	a subserves
Tank problem RNO-16	Port deled
	Court Cont
	(84.)
	Kar
01	Signature of Lab incharge / HOD
Signature of Maintenance Incharge	
	THE PERSON NAMED IN COLUMN TWO
The second secon	

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Mess and BH-I Problem Reported On: 16/12/20 Problem

Time:

Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
	BHILIside ball room tar water Leakage Problem	- BH-Z	Maldory
2	Acquaguard Pipe Leakage Problem	- BH-M	Solus Jein

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF ECE

Problem Reported On: 16(12) 2020 Time: 10 ! 4

Problem Attended On:

Time:

	Tille, 101 40		
S.No.	Name of Work / Problem	Location	Action taken / Remarks
1.	wshabain pipe	Student toil	AS.
2-	. 11	Hod side	
		1	· mules

Signature of Maintenance Incharge

Signature of all Indharge HOD Dept. of ECE

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF Problem Reported On:

G.H I 16/12/20

Problem Attended On

Time: 10-00 am

Time:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
5.110.	ABuaguard Water Pipe leak	Mess. On H I	Corpleted when 120
			To The state of th

re of Maintenance Incharge

Signature of Lattencharge/HOD

Dt.-11.12-20 ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF A PSSDC Problem Reported On: Problem Attended On : Time Action taken / Remarks Name of Work / Problem Room pipe like Leekge

y Fire Exteriosed Loter
order pipe leekge Signature of Lab Incharge/HOD Signature of Maintenance Incharge TYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 111120 Problem Attended On: Time: Action taken / Remarks Location Name of Work / Problem S.No. Lavatory out side pipe damage mess trut sile Hand wash tarcar Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) 15/12/20 Problem Attended On **DEPARTMENT OF** Gr. H Problem Reported On: Time: 10 .00 am. Action taken / Remarks Location Name of Work / Problem is broken and floor GIHI Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CES Problem Reported On: 5121 Problem Attended On Time: Time : S.No. Name of Work / Problem Location Action taken / Remarks Genta Toilet United Tap Dutitor IRlock water Tap B-Block Inthory water filter tecking C-Block-Grand How (Gurls Torlet) Bathreon Water Tap beauting Signature of Maintenance Incharge Signature of Lab Incharge (140 M.O.D.-E.E.E. Ded ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF 34-3 Problem Reported On: 05 112 Problem Attended On: Time: Action taken / Remarks S.No. Name of Work / Problem Location Hostel- 3 Hoste-3 Motor under Grand Pipelin Signature of Maintenance Incharge Signature of Lab Incharge / HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOY'S HOSTAL- 3 Problem Attended On: 08/00 Problem Reported On: Time: Time: Action taken / Remarks Location Name of Work / Problem S.No. Front Side Signature of Lab Incharge/HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Reported On: 25/1/2) Problem Attended On Time: -Time: 12-01 NOVI Action taken / Remarks Name of Work / Problem S.No. N nead of the Departme Signature of Lat lincharge / HOD Signature of Maintenance Incharge ya Institute of Technology f DITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 25/1/2-1 Time: 10-30 Problem Attended On: Time: Action taken / Remarks Location Name of Work/Problem S.No. Pluber completed R.NO. 38 Ball room Two in one _ BH-3 Tap. is broken R.NO-38 Signature of Labincharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL- II Problem Attended On: Problem Reported On: 25/1/21 Time: 10-30 Time: Action taken / Remarks Location Name of Work/Problem ar) (GIF), Redilier Commay bath room tap broken BH-2 working (steal ras) Acquaquartis_ BH-Signature of ab Incharge/HOD nature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 191121 Problem Attended On: Time: Action taken / Remarks Name of Work / Problem S.No. R-NO-02 810 Plus Tank Problem R.NOS- 020Wd-10 Signature of Lab incharge / HOD gnature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF POLY July Problem Reported On: 22 | 51 | 2021 Problem Attended On: Time: Action taken / Remarks Name of Work / Problem Location S.No. 1 water leaved for Refrigult) Diploma Signature of L nature of Maintenance Incharge Polytechnic ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT **TEKKALI** SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On: 23/1/21 Time: Time: 12.0000 Action taken / Remarks Location Name of Work / Problem S.No. supply E-Black

ture of Mathtenance Incharge

ne Department

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTEL

Problem Reported On:

15/02/21

Problem Attended On: Time:

Name of Work / Problem	Location	Action taken / Remarks
Side batts		BH-I
	b Ground F	side batts Room tap

ignature of Maintenance Incharge

rge/HOD Signature of

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BOYS HOSTEL

Problem Reported On:

16/02/21

Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1	Dat Floor left	- side wash	BH-I
	basin Walts	Pipe damage	
2	R-33 Flus	b tank is	BH- 11
_	damaged		necre da

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

TYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On:

G. H 17/2/21 Problem Attended On:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
	Wash room tap is broken	GH2 1st floor.	Reddie Partition

gnature of Maintenance Incharge

Signature of Lab Incharge HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

TEKKALI SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF CIVIL

Problem Attended On: Time:

Name of Work / Problem	1.ocation	Action taken / Remarks
	E-BLOCK	1 04
Supply.	· CIVIL DEPT	OS was
		Rukpatrail
		Bristog.

Signature of Maintenance Incharge

Heled of the person good on

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL) HOSTEL

DEPARTMENT OF BOYS Problem Reported On:

13/02/21

Problem Attended On: Time:

S.No.	Name of Work / Problem		lame of Work/Problem Location		Action taken / Remarks	
1	R-6		1	8 inching	BH- III plumker 1000°C is completed Chry	

gnature of Maintenance Incharge

Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF BC6

Problem Reported On: 13 2121

Problem Attended On:

Time: Time: 121 10

	Time: TETT		Action taken / Remarks
S.No.	Name of Work / Problem	Location	
100000000000000000000000000000000000000	Staff Toilet	stff roll.	A salala)
	Drinking water	SF- Coridor HOD	2 201/2/21

Signature of Maintepance Incharge

Dept. of ECE

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) 5/2/21 DEPARTMENT OF Problem Attended On Time 10-45 am. G. H. Problem Reported On Time: Action taken / Remarks Name of Work / Problem Tap leak problem Room 9 GHZ do es Hot wate lap not Ground flow - GHZ 13. Niry working. 3 Hot water tap lease 1st floor-Gittz _ Signature of Lablacharve HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CIVIL ENGG. Problem Attended On Time 05-02-2 roblem Reported On: Action taken/ Remarks Time Location Name of Work/ Proplem Water Basin & BLOCK (Sinc) GROUND Pipe problem FLOOR No. Signatur Head of the Depa repartment of Civil Engl ATTAM, TEKKALI, are of Maintenance Inchange WIE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOX'S HOSTAI - I Problem Reported On: 06 2 2 Problem Attended On: Time Time: 10 - 30 Action taken / Remarks Location Name of Work / Problem S.No. Bathroom tap Signature of Lab Incharge/HOD

Signature of Maintenance Incharge

77

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Reported On Time: 02/07/47 Problem Attended On: Time Action taken / Remarks Location Name of Work / Problem S.No. R-1 Hand wash BA-11 water Corrier Wall broken Signature of Lab Jorburge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On 0/2/21 Problem Reported On Time Time 10:35 am Action taken / Remarks Location Name of Work / Problem S.No. attached washion Room - 31 water flowing sink 75 stray G1H2plate broken. Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) Problem Attended On DEPARTMENT OF 668 Problem Reported On: 3 | 2 | 2 0 2/ Time Action taken / Remarks Time: 11: 00 14 Location Name of Work / Problem SF- A'Rhe S.No HOP Sir Side Carridan. Signature of Lab Incharge | HOD Dept of ECE ance Incharge

Signature of Mainter

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

30 11/21

Problem Reported On:

Time: 11-00 am

GH2

Problem Attended On: Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1	Hot water tapis	and floors. Cott2	10101
2	broken - wash basin Tap is	2nd floor-GHZ	L Consporting
		1st +100x - G142	

4 solar system is not working

Signature of Maintenance Incharge

Signature of Lab Incharge / HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF CE Problem Reported On: 17/02/21 Problem Attended On: Time: Time: 09100-144 Action taken / Remarks Location Name of Work / Problem 194 Floor A Block 01) GENTS BATHROOM 1st Floor winal pois PIPE (Push Buston) Nat wark Recedon Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL TIL Problem Reported On: 19/2/2/ Problem Attended On: Time: 10:30 Action taken / Remarks Location Name of Work / Problem S.No. 1. Baltyoon hand R.NO.22 pressure Pipe is (BH-III) not working 2 Water tap is (BH-11) not working properly Signature of Lab Incharge/HC Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI . SERVICE CALL REPORT (COUNTER FOIL) Problem Attended On: **DEPARTMENT OF** Problem Reported On: BOXS HOSTEL Time: Time: 22 02 21 Action taken / Remarks Location Name of Work/Problem Single common both room tap broken ItsFloor prige walts is not coming S.No. Signature of Lab lacharge/HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On: 22/3/21 Time Name of Work / Problem Action taken / Remarks S.No. FTIZ is foundly sound not Signature of Maintenance Incharge Signature of Lab Incharge/HOD ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF Problem Attended On: Problem Reported On Time: Time: 10-30 am Action taken / Remarks Location Name of Work / Problem S.No. Ground floor GHZ Tap is broken Signature of Lab ligharge/HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF 29/3/21 Problem Attended On: Problem Reported On: Time: Time: 10 30 am. Action taken / Remarks Location Name of Work / Problem S.No. and floor 1 Tap is broken GHI in washroom

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI DEPARTMENT OF BOYS HOSTAL TOWN THE FOIL Problem Reported On: 06/3(24) Time: 10-30 Problem Attended On Time: Action taken / Remarks Name of Work / Problem Common ball BUT Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTAL-I Problem Attended On: Time: Action taken / Remarks Name of Work / Problem Location S.No. BH-I Back pectical Signal side Ballyrom waste water manual over How. Signature of Lab Incharge/HOD Signature of Maintenance Incharge TITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI ERVICE CALL REPORT (COUNTER POIL) OF Boys Hoslar - 2 8 3 Problem Attended On: 1: 22/3/21 Time: 10.30 Action taken / Remarks Name of Work / Problem Location BH-3 RNO-12 - Common balts rom tap broken Signature of Lab Incharge/HOD Signature of Maintenance Incharge

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) Problem Reported On: 03/4/21 Problem Attended On Time: Action taken / Remarks Name of Work / Problem Tap is broken p. No.37 (attached bath your) BH-2 2. Comman bath roose. (8/1)-BH-2 3. wash basin center BH-2 (GIF) Acquaguard water Control switch is not working - Mess Signature of Lab Incharge / HOD Signature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF, GH Problem Attended On: Problem Reported On: 15 |04|21 Time: Time: 11'30 Action taken / Remarks Name of Work / Problem Location S.No. wash room Tul Signature of Lab Incharge / HOD nature of Maintenance Incharge ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI SERVICE CALL REPORT (COUNTER FOIL) DEPARTMENT OF BOYS HOSTEL Problem Attended On: Problem Reported On: 22/04/21 Time: Action taken / Remarks Location Name of Work / Problem S.No. Tap is not working I Floor First room bott room common bott rooms threa(3) taps broken I Floor Ground Ploon Signature of Lab Incharge/HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT TEKKALI

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF E.C.E

A Block

Problem Reported On: Ladies Toilets (FF-04) Problem Attended On:

Time: 10.306 5 21

Time:

S.No.	Name of Work / Problem	Location	Action taken / Remarks
1,	No comode	A/FF-04	
2,	Tap leakage	1 /	A so
3,	water Blocked In Toilets.	" /	40
4	Washberton pipe	stoff wathran	

Signature of Maintenance Incharge

Sig 190 e of Lab Incharge /HOD

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT

SERVICE CALL REPORT (COUNTER FOIL)

DEPARTMENT OF

Problem Reported On: Time: APSSDC - PSlock
Prol
30 PC 5 21 Prol

Problem Attended On:

S.No.	Name of Work/Problem	Location	Action taken / Remarks
1	Water problem		
2	sink damaged	APSSDL	
PROGRAMME IN		F block	
3	Tap problem		
		M	

Signature of Maintenance Incharge

Signature of Lab Incharge/HOD

The Admin inchange AITAM Telepali

Sub: Lenovo monitor and D-Lohne not working. Sir,

I am (4. APPALARAJU) a computer programmer in eee department. In my computer lab 3 lenovo monitors, one mother board and D-Link switch allier (12269) are not working please replace these

Thanking yoush,

Forwarded & system about

Green as under

(Hernas Under)

2911 resulting the man

(Hernas Under)

(Hernas Under)

(Hernas Under)

(Hernas Under)

yours faithfully

Dept. of E.E.E.

sitya Institute of Technology f

Management, TERRALI

To The Director, AITAM, Tekkali. Respected Sir,

Sub: - Request for replacement of computer key board mouse – CGC - Reg.

I am (S. Bhaskara Babu) working as Asst. Professor (Student Counselor) in our esteemed organization from 02/08/2010.

I was given a Lenovo Desktop, Keyboard and Mouse in 2010. I would like to bring to your kind notice that after several years of usage, the keyboard became stiff and it is not supporting properly. Sroller of the mouse is also not in working condition. As I am also looking after CGC, Alumni, R & D & EBSB cells proper equipment with latest configuration is a much needed for me to complete the tasks on time. Desktop system is in good condition, hence it is not required at present.

Apart from the above, if possible I also request you to provide a printer (Now a days, funding agencies and JNTU are asking for the scanned documents).

I request you to kindly grant the required accessories for completing the assigned tasks on time. Thanking you,

Sus and south

Yours sincerely,

(Bhaskara Babu Suthroy)

hand rough!

86

To
The Inchange
System Admin Depoterments
Af TAM
Terreli

from

R. Chardramohan
Caypus tofr HC
parinfthi hart.

ALTAM
TELAKOLI

Respected 818, Request for Keeping the Eystein of.

Pavinisti had in works group Reg.

[(R. CHANDHAMOHAN) Caupus Soft \$1/C. Woodlag in Down 14th has. During the company exams and has closes. Facing lot of issues. I cannot able to rently the problems due to the syltems in the college domain the problems due to the syltems in the college domain so I knowly sneavest you to keep the syltems in workagenous only.

In. Charge (Finishing School)

TEKKALI
TEKKALI
TEKKALI
TEKKALI
TEKKALI

Training & Pracement Officer

Sol solved for

ous Charlamohans

87

To,

The System Administrator

AITAM, TEKKALI,

Subject: Requesting you to provide hardware components and internet access at Student Activity Center.

Respected Sir,

We are the team of SAC writing this letter to request you to provide us the following hardware and access to Internet for the smooth functioning of Learning Activities of Club students in our Student Activity Center.

We attached the tabular details of requirements for your reference. Please consider our request and do the needful at the earliest possible.

S.No	Hardware Name	Quantity
1	Power Cables for Desktop	2
2	VGA Cable for Desktop	1
3	Wired Mouse	3
4	Epson Printer	(1)

Thanking You Sir,

Regards,

(J.Suresh Kumar)

In charge, SAC

Andres (1, borns)

ADITYA INSTITUTE OF TECHNOLOGY AND MANAGEMENT, TEKKALI DEPARTMENT OF NBA

Tekkali, Date: 16-02-21.

To

The Incharge, Systems Administration Dept., AITAM, Tekkali.

Sir,

NBA office computer hard disk are not working properly. So please arrange the new Hard disk.

Yours Sincerely

10

M: 02-02-2021, Tekkoli.

The System Admin Incherse, ALTAM College, Tekkeli.

Sub: Required 2 methers boords and 8 moniters.

Siv,

I CK. prosedbolow) working of Computer - Programmer in CSE Dept. Siv in my Less (Sy stemy progremming (eb) systems not werking proporty. Seconse of Two mother boards problem and 8 maniter display großlem. so pleise solve tris problem as Early as Thomain you so

Possible.

please really the yours firthfully Problems at un carbier K. prusedbeby, progremmer, CSE.

Head, Dept. of CSE Aditya Institute of Technology & Management Tekkali-532 201, (A.P.)

Tekkali Dt:06/04/21

The Director, AITAM Telkali

Sub: Request to provide Laptop to placement
cell to conduct technical training
Respected Son,

Inother to provide trainings to students in lettest technologies like AWS, GCP, TIL, AI, Solutionae etc., lettest technologies like AWS, GCP, TIL, AI, Solutionae etc., lettest technologies with 8GB RATI, IS processor, ITBHDD We need a laptic with requestry you to provide the Inthis regard, herewith requestry you to provide the same as early as possible. A sample questrion for some as early as possible. A sample questrion for some as early as possible is attached with this letter for your two laptic models is attached with this letter for your two laptic models.

Thousing Your

2016 May 20 May

Yours faith fully, Trankle (Dr. TN V 35 Kumas) The Distect 81 ATTAM Telalachi

Respected Stat.

We, D. Pavani & B. V. N. Muriy Retrostre are working in your office. For Transfer centificates and Student related centifictes were to brugaring by us. But due to Hard Disk Problem # 98 taking long time to issued centilicates whiting the ime. Therefore we are henewith enequesting you to such suppose he system and we need from 2 systems can be PSIOCESS the T.C and Other certificates with the both Systems Tranking You Sist.

Yours balltabully. - Pavar Barrighthouse (B.N.N. MURRY Ednates)

Dt. 31.12-2020

The System Actions Durchange Al TAM Tekkali

Dear 80,

Sub: Request for replacement & System soroux- Reg

Lang here with rescreety you to replace only ensteen more for a regular use. present only more is not worker.

Thauling you So

Yours taithouth Scept of VEOLD Praced Advoranced whe other

Date: 04.02.2021

To

The Incharge,

System Admin Dept.

AITAM, Tekkali.

Sir,

Sub: Regarding 2 Computers, 2 Monitors, Ram, UPS – BS&H Department.

For smooth working of the Department, there is a requirement of 2 Monitors & a Ram at BS&H Department Library and a UPS for the computer assigned to Physics In charge at E-Block. Two new Computers for Head of Department (HoD) BS&H and Clerk BS&H Department to be replaced the old Dell Computers.

Chouse of Marian (" Wall hand "

HoD, BS&H

Head of the Department
Basic Tace and Humani

And Management Televill-532 201

The Director,

Adilya Institute of Technology and Management,

Tekkali,

Srikakerlam.

Sub: Requisition - LCD Projector - New Projector - .. regd.

9 am, N. Murali, working as Assistant Professor of English and Lab-In-charge of English Language Lab, Block-E. Jany Very sorry to bring to your kind notice about poor function -ing of LCD projector that has been provided by the extremed management of own college for which we would be grateful. The above said projector has been in very good functioning condition. But, Now it has lost its projecting quality and its screening quality.

Hence, I nequest your highness to kindly consider my plea and take an Emmediale action by providing a Grood projector (i.e New) for smooth nunning of labsessions. For which we would be grateful to you.

Thanking you sir,

00/

Yours faithfully, N. Hali CH. Murali) Asst. Professor

I ab-In-charge (E-Black,

Tekkali. Dt: 24/04/21

TOI

The System Incharge,

ATTA MI

Tekkali.

subr Two mouses are not working.

Sir,

D' (programmer) CSE Dept. In.

Advanced programming lab (FF-16, D Block)

two mouses are not working property

so please replace the mouses.

Thanking you,

Aditya mstifute Tochnology & Manage. Ina Tekkali-532 201, (A.P.)

Yours faithfully,

A.V. Santosh Kumar programmer,

gy/12/21 CSE Dept.